POWER SYSTEMS
750-A P.B.X. PLANT
CHARGE AND DISCHARGE CIRCUIT
WITH RELAY FOR CHARGE CONTROL

D.W.C. ISSUE	C.O. ISSUE
1-1-XXXX	1-1-XXXX



CIRCUIT NOTES:

101. PROVI TO ISSUE 9-D, "A", "B", "W", & "Z" WIRING WERE NOT SHOWN AND "A" & "Z" WIRING WERE PART OF FIG. 1.

102. FURNISH "W" AND EITHER "A" OR "B" WIRING AND APPARATUS FOR CHARGE CONTROL BY VOLTAGE. "B" WIRING AND APPARATUS IS REQUIRED ONLY IF CHARGE RATE AT OPERATE VOLTAGE OF (CC) REL. IS OVER 0.5 AMP. STRAP 26TH PART OF (RS) RES. WHEN C.O. BAT. IS 24V. FURNISH "A" AND "Z" WIRING AND APPARATUS WHEN CHARGE CONTROL BY VOLTAGE IS NOT PROVIDED.

EQUIPMENT NOTES:

201. ALL LEADS TO BE 22 D.S. & C.C. UNLESS OTHERWISE SPECIFIED.

202. FURNISH "Y" WIRING & APPARATUS AND OMIT "X" WIRING IF IT IS NOT POSSIBLE TO LIMIT HIGH CHARGE RATE BY SELECTION OF CENTRAL OFFICE FEEDER VOLTAGE OR NUMBER OF FEEDER CONDUCTORS. FURNISH 10Ω RESISTOR WITH 24V. FEEDERS. 35Ω RESISTOR WITH 48V. FEEDERS.

203. SPECIFY RES. PWR. DATA SECT. 14.22, SHEET 3, ITEM 303. TOTAL OHMS 30, WITH TAP AT 26TH TO CARRY ½ AMP. THRUOUT.

PRINTED IN U.S.A.

SD-80477-01

SD-80477-01 750A PBX PLANT CHARGE AND DISCHARGE CIRCUIT WITH RELAY FOR CHARGE CONTROL

POWER SYSTEMS

CIRCUIT REQUIREMENTS

SD-80477-01

APPARATUS DESIG.	APPARATUS CODE	MECH. REQ. BSP FIG.	MECH. REQ. CONT PRESS	MECH. REQ. ARM STRVL	CIRCUIT PREPARATION SEQ SW POS.	CIRCUIT PREPARATION BLOCK	CIRCUIT PREPARATION TEST CLIP DATA CONN. BAT	CIRCUIT PREPARATION TEST CLIP DATA CONN. GRD	TEST SET PREP	SEE TEST NOTE NO.	DIRECT CURRENT FLOW REQ. TEST WDG.	TEST FOR	AFTER SCALE AMP	TEST AMP.	READ AMP.	REMARKS
FIG. 1 RELAYS IN APPARATUS																
CA	R6028	3/1		.020				2RT(CA)	GRD.					.009	.0086	
CC	2558					(CA) Q				1						
2 APPARATUS																
CT	C1584	1/1	H	.015								Q		.0110	.0098	

TEST NOTES:

1. REMOVE (CHG) AND (PWR BB) FUSES. CONNECT RING ON "BAT. & GRD." JACK OF 35 TYPE TEST SET TO BAT. TERM. 1 FOR CABLE PAIR CHARGE OR TO RHEO. FUSE IN SERIES WITH DRY CELLS FOR LOCAL CHARGER. CONNECT TIP ON "TIP & RING" JACK TO 3T(CA) RELAY. CONNECT VOLTMETER ACROSS 3T(CA) RELAY AND GRD. TERM. 1. ADJUST IN ACCORDANCE WITH BSP.

CKT ASS. NO. 1 2 3 4 5 6 7 8 9 10 11

SD-80477-01

POWER SYSTEMS
750-A E&A X PLANT
CHARGE AND DISCHARGE CIRCUIT
WITH RELAY FOR CHARGE CONTROL



EQUIPMENT NOTES
SEE ALL LEADS TO BE #19 B.S. & C.C. UNLESS OTHERWISE SPECIFIED.

CIRCUIT REQUIREMENTS

CIRCUIT NUMBER		SPECIAL REQ.			CIRCUIT PREPARATION			CIRCUIT FLOW REQ.					REMARKS
FROM	TO	WIRE TYPE	CONT. RESISTANCE	HARNESS POS.	BLOCK	TEST CLIP DATA CONN. & TERMINAL		SEQUENCE NO.	CIRCUIT CLASS	CIRCUIT CAT.	CIRCUIT FLOW	TEST AMP.	READ AMP.	
P201														
J201														
1	GND	TZ1	W	015						0		870	0.86	

SD-80477-01